



INSPECTION SUMMARY

Nissan X-Trial 2023

JN8AT3MTXPW003775 | 28528 KM | GCC Specs

VEHICLE SPECIFICATIONS

MAKE Nissan	MODEL X-Trial	YEAR 2023	VIN / CHASSIS JN8AT3MTXPW003775
MILEAGE 28528 KM	SPECIFICATIONS GCC	KEY 1 Key	NO. OF CYLINDERS 4
BODY TYPE SUV	SEATING CAPACITY 5 Seats	FUEL TYPE Petrol	ENGINE CC 1500 CC

SECTION SUMMARY SCORES

ENGINE & TRANSMISSION 100.0% 21/23 rated	FRONT 90.9% 11/11 rated	RIGHT SIDE 95.0% 10/10 rated
BACK / REAR 100.0% 8/8 rated	LEFT SIDE 95.0% 10/10 rated	ROOF 100.0% 4/6 rated
FRONT INTERIOR 100.0% 8/10 rated	BACK INTERIOR 100.0% 8/10 rated	DASHBOARD 100.0% 16/16 rated
SUSPENSION & STEERING 100.0% 14/16 rated	BRAKE 100.0% 9/9 rated	CHASSIS & ACCIDENT 100.0% 9/9 rated
EXHAUST & EMISSIONS 100.0% 5/7 rated	TIRES & WHEELS 100.0% 7/7 rated	SAFETY SYSTEM (AIRBAGS) 90.0% 10/12 rated
FEATURES & OPTIONS 100.0% 11/30 rated	ROAD TEST 94.4% 9/9 rated	

Score basis: Pass 100 | Attention 50 | Fail 0 | N/A excluded

CUSTOMER & INSPECTION DETAILS

Customer: Rehman Siddiqui | Mobile: 0547299077 | Plate: Hayaza | Inspector: Muhammad

VEHICLE PHOTOS



FR left side



Front



FR right side



RR right side



Trunk



RR left side



Roof



FR interior



RR interior



Dashboard



Multimedia



Instrument cluster



Key



Spare wheel




Rim / Wheel



Engine bay



VEHICLE BODY CONDITION DIAGRAM



MARKED BODY PANELS

Bonnet / Hood	P • S
Left Front Fender	S
Right Front Fender	D1
Left Front Door	D1
Right Front Door	D1
Right Rear Quarter	D1

CODE MEANINGS

XX	Replaced	D1	Minor Dent	D2	Major Dent
S	Paint Shower / Spray Only	P	Poligate Repaired		

INSPECTOR COMMENTS & RECOMMENDATION

Car has front minor accident. Steering and dashboard both airbag deployed.

COMPLETE INSPECTION CHECKLIST

ENGINE & TRANSMISSION

Cold start performance	PASS
Engine oil level / condition	PASS
Radiator	PASS
Condenser	PASS
Fan assembly	PASS
AC Compressor	PASS
Battery	PASS



Engine mounts	PASS
Belts and hoses	PASS
Air filter box	PASS
Engine head oil leakage	PASS
Engine block oil leakage	PASS
Engine oil pan leakage	PASS
Alternator	PASS
Engine head noise	PASS
Engine crank noise	PASS
Engine vibration	PASS
Engine wiring	PASS
Supercharged	NA
Turbocharged	NA
Transmission oil leakage	PASS
Transmission mount	PASS
Transmission noise	PASS

FRONT

Bumper	ATTENTION
Bumper grill	PASS
Bumper Reinforcement	PASS
Hood / Bonnet	ATTENTION
Upper support	PASS
Lower support	PASS
Right headlamp	PASS
Left headlamp	PASS
Windshield	PASS
Wiper	PASS
Windshield washer	PASS

RIGHT SIDE

Fender	PASS
Front door	PASS
Rear door	PASS
Quarter panel	ATTENTION



Side mirror	PASS
Foot panel	PASS
A pillar	PASS
B pillar	PASS
C pillar	PASS
D pillar	PASS

BACK / REAR

Right tail-lamp	PASS
Left tail-lamp	PASS
Trunk	PASS
Bumper	PASS
Trunk floor	PASS
Rear windshield	PASS
Rear wiper	PASS
Rear windshield washer	PASS

LEFT SIDE

Quarter panel	PASS
Rear door	PASS
Front door	PASS
Fender	ATTENTION
Side mirror	PASS
Foot panel	PASS
A pillar	PASS
B pillar	PASS
C pillar	PASS
D pillar	PASS

ROOF

Right Roof rail	PASS
Left Roof rail	PASS
Roof	PASS
Roof Lining	PASS
Sunroof	NA



Panoramic Roof	NA
----------------	----

FRONT INTERIOR

Front right seat condition	PASS
Front right electric seat	NA
Front left seat condition	PASS
Front left electric seat	NA
Front right seat belt	PASS
Front left seat belt	PASS
Front Flooring Matt	PASS
Right door panel	PASS
Left door panel	PASS
Front interior roof light	PASS

BACK INTERIOR

Rear right seat condition	PASS
Rear right electric seat	NA
Rear left seat condition	PASS
Rear left electric seat	NA
Rear right seat belt	PASS
Rear left seat belt	PASS
Rear Flooring Matts	PASS
Right door panel	PASS
Left door panel	PASS
Rear interior roof light	PASS

DASHBOARD

Dashboard condition	PASS
Steering wheel condition	PASS
Steering wheel control	PASS
Combination Switch (headlamp/Indicator)	PASS
Instrument Cluster	PASS
AC vents (Right)	PASS
AC vents (Middle)	PASS
AC vents (Left)	PASS



AC control panel	PASS
Air Condition Cooling	PASS
Multimedia	PASS
Center console	PASS
Gloves box compartment	PASS
Rear view mirror	PASS
Right Sun Visor	PASS
Left Sun Visor	PASS

SUSPENSION & STEERING

Front right shock absorbers	PASS
Front left shock absorbers	PASS
Rear right shock absorbers	PASS
Rear left shock absorbers	PASS
Front right control arms	PASS
Front left control arms	PASS
Suspension bushes	PASS
Ball joints	PASS
Steering rack leakage / play	PASS
Steering box	PASS
Power steering	PASS
Wheel bearings and noise	PASS
Wheel alignment	PASS
Suspension road-test response	PASS
Front Air suspension	NA
Rear Air suspension	NA

BRAKE

Front Right Brake Pad	PASS
Front Left Brake Pad	PASS
Rear Right Brake Pad	PASS
Rear Left Brake Pad	PASS
Brake Calipers	PASS
Brake Fluid Level / Condition	PASS
Brake Fluid Leakage	PASS



Parking Brake / Handbrake	PASS
---------------------------	------

ABS System	PASS
------------	------

CHASSIS & ACCIDENT

Front right chassis rail	PASS
--------------------------	------

Front left chassis rail	PASS
-------------------------	------

Right apron / inner fender	PASS
----------------------------	------

Left apron / inner fender	PASS
---------------------------	------

Rear right chassis rail	PASS
-------------------------	------

Rear left chassis rail	PASS
------------------------	------

Floor pan and underbody	PASS
-------------------------	------

Undercarriage	PASS
---------------	------

Flood / water damage	PASS
----------------------	------

EXHAUST & EMISSIONS

Exhaust Manifold	PASS
------------------	------

Intake Manifold	PASS
-----------------	------

Catalytic Converter	PASS
---------------------	------

Exhaust Mounts/Hangers	PASS
------------------------	------

No Smoke	PASS
----------	------

White Smoke	NA
-------------	----

Black Smoke	NA
-------------	----

TIRES & WHEELS

Front Right Tire	PASS
------------------	------

Tire Manufacturing Year	2022
-------------------------	------

Front Left Tire	PASS
-----------------	------

Tire Manufacturing Year	2022
-------------------------	------

Rear Right Tire	PASS
-----------------	------

Tire Manufacturing Year	2022
-------------------------	------

Rear Left Tire	PASS
----------------	------

Tire Manufacturing Year	2022
-------------------------	------

Spare Tire	PASS
------------	------

Wheel / Rim Condition	PASS
-----------------------	------

Took Kit	PASS
----------	------



SAFETY SYSTEM (AIRBAGS)

Driver Airbag	ATTENTION
Driver Knee Airbag	PASS
Passenger Airbag	ATTENTION
Passenger Knee Airbag	PASS
Driver Seat Side Airbag	PASS
Passenger Seat Side Airbag	PASS
Rear Seat Airbag	PASS
Right Curtain Airbag	PASS
Left Curtain Airbag	PASS
Right D Pillar Airbag	NA
Left D Pillar Airbag	NA
Airbag Warning Light	PASS

FEATURES & OPTIONS

Push Button Start	PASS
Keyless Entry	NA
Remote Start	NA
Cruise Control	NA
Adaptive Cruise Control	PASS
Lane Departure Warning	NA
Lane Keep Assist	NA
Blind Spot Monitoring	NA
Forward Collision Warning	NA
Automatic Emergency Braking	NA
Front Parking Sensors	NA
Rear Parking Sensors	PASS
Front Radar	NA
Rear View Camera	PASS
360° Camera	NA
Navigation System	NA
Apple CarPlay	PASS
Android Auto	PASS
Bluetooth	PASS

Seat Memory	NA
Heated Seats	NA
Cooled Seats	NA
Electric Folding Mirrors	NA
Traction Control	PASS
Power Windows	PASS
Electronic Parking Brake	PASS
Auto Hold	PASS
Climate Control AC	NA
All Wheel Drive (AWD)	NA
4 Wheel Drive (4WD)	NA

ROAD TEST	
Engine Performance / Acceleration	PASS
Transmission Shifting	PASS
Gear Shift Delay	PASS
Gear Shift Jerk	PASS
Steering Performance	PASS
Brake Performance	PASS
Brake Noise	PASS
Abnormal Noise While Driving	PASS
Dashboard Warning Lights During Test	ATTENTION

ISSUES & FINDINGS

ATTENTION **Bumper**
Painted

ATTENTION **Hood / Bonnet**
Poligated Painted

ATTENTION **Quarter panel**
Scratch

ATTENTION **Fender**
Painted



ATTENTION

Driver Airbag

Replaced

ATTENTION

Passenger Airbag

Replaced

ATTENTION

Dashboard Warning Lights During Test


Engine check light ON



DAMAGE PHOTOS



Damage photo 1



Damage photo 2



Damage photo 3

SIGNATURES



Inspector signature



Customer signature